Fig. 1




Fig. 2




Fig. 3







Fig. 4





ELECTRONIC DEVICE 05/26/05
Ikeda et al. - 1912.72793
Greer, Burns & Crain, Ltd. (Patrick G. Burns)
Sheet 5 of 34 (312) 360-0080

5/34



(B)

### EFFECT ON GAIN OF REMOVING SCREW THREADS







Fig. 6






. Fig. 7




PART OF SCREW THREADS CUT



#### ELECTRONIC DEVICE 05/26/05 Ikeda et al. - 1912.72793 Greer, Burns & Crain, Ltd. (Patrick G. Burns) Sheet 8 of 34 (312) 360-0080

8/34

Fig. 8



(B.)

	BEFORE CHANGE	AFTER CHANGE	NO 10° CONTACT POINT
RESONANT FREQUENCY (KHz)	41.4	41.6	40
GAIN (dB)	-48.69	-48.16	-45.9
BANDWIDTH (Hz)	7845	7412	5832
Q	5.24	5.47	6.82

Fig. 9





Fig. 10

ANTENNA GAIN VERSUS L VALUE



10/34.

Fig. 11

### ANTENNA GAIN VERSUS NUMBER OF COIL TURNS






Fig. 12





ANTENNA OUTPUT

Fig. 13






Fig. 14





Fig. 15






Fig. 16




Fig. 17




Fig. 18




Fig. 19




Fig. 20




Fig. 21




Fig. 22





Fig. 23



## 


Fig. 24

	BEFORE CHANGE	AFTER CHANGE
RESONANT FREQUENCY (KHz)	41.9	41.7
GAIN (dB)	-49.86	-49.47
BANDWIDTH (Hz)	8305	8253
DANDHIDI: (III)	5.00	5.02
<u> </u>		

Fig. 25


	BEFORE CHANGE	AFTER CHANGE
	41.9	41.3
RESONANT FREQUENCY (KHz)	-49.86	-49.3
01122.	8305	7959
BANDWIDTH (Hz)	5.00	5.18
<u>Q</u>		

Fig. 26



		BEFORE CHANGE	AFTER CHANGE
	RESONANT FREQUENCY (KHz)	41.9	41.8
(B)	GAIN (dB)	-49.86	-49.3
(1)	BANDWIDTH (Hz)	8305	7806
100	DANDWIDIN ()	5.00	5.25
	<u>¥</u>	L	

Fig. 27







Fig. 28



# 

Fig. 29

	MASS PRODUCTION	MASS PRODUCTION PRE-PROPRODUCTION				PRE-PRODUCTION
	SAMPLE A	SAMPLE B	SAMPLE C	SAMPLE D Ti	SAMPLE C SAMPLE D TI SAMPLE E SS SAMPLE F	SAMPLE F
RESONANT FREQUENCY (KHz)	40.9	41.2	41.2 41.3	41.8	41.0	41
GAIN (dB)	-47.7	-48.77	47.4	-51.3	-49.54	-44.5
BANDWIDTH (Hz)	7130	6091	9619	8239	7351	4704
Ö	5.69	5.35	99*9	5.07	95*5	8.67

ELECTRONIC DEVICE 05/26/05
Ikeda et al. - 1912.72793
Greer, Burns & Crain, Ltd. (Patrick G. Burns)
Sheet 26 of 34 (312) 360-0080
26/34

Fig. 30


	SAMPLE D Ti		SAMPLE E SS	
	BEFORE CHANGE	AFTER CHANGE	BEFORE CHANGE	AFTER CHANGE
RESONANT FREQUENCY (KHz.)	41.8	41.6	41.0	40.4
GAIN (dB)	-51.3	-48.7	-49.54	-46.8
BANDWIDTH (Hz)	8239	6877	7351	6434
0	5.07	5.99	5.56	6.27

Notes: bolting torque is fixed 3 N·m.

Fig. 31

	no cut			cut part		cut part
RESONANT FREQUENCY (KHz)	41	61.6	40	59	41.3	61.2
ref(dB)	-48.8	-48.8	-45.96	-46.3	-48.1	-48.2
ΔF	7928	13798	5816	11090	7309	13213
Q	5.14	4.42	6.86	5.3	5.55	4.6

Fig. 32



	ANGLE	LENGTH (B)	RATIO (B/A)
(C)	10	2.614617	0.217885
	30	7.76441	0.647034
	50	12.6783	1.056525
	120	25.98043	2.165036
	180	30	2.5

Fig. 33





Fig. 34







Fig. 36







Fig. 38



34/34

Fig. 39




Fig. 40





Fig. 41



# This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

# IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER: \_\_\_\_\_

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.